

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 1036

Dated: 25/06/2025

It is certified that the existing building **Gurukul Public School** (name of the building or premises) at **Harpur Pepeganj, Gorakhpur** (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1					

The building is owned/occupied by **Gurukul Public School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (Name of Department/ Govt.) on 25.06.2025 (date of inspection) in the presence of LAKSHMAN PRASAD VISHWAKARMA (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 25/06/2025 for a period of **10 years** in accordance with rule and subject to compliance of the specific conditions as appended.

- 1
- 2
- 3
- 4

Issued on 25/6/2025 at Gorakhpur by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 


Name : Ravi Singh

Designation : Assistant Engineer

Name & Address of Department/ Office: PD, UPPWD  
Gorakhpur

Copy

**Manager**  
**Gurukul Public School**  
Harpur, Pepeganj, G.

  
**PRINCIPAL**  
**GURUKUL PUBLIC SCHOOL**  
HARPUR, PEPPEGANJ